

Figure - Bug #118830

【AF】 【EVT3】 【Monkey】 110（616）版本Monkey测试18小时后异常停止且不进屏保

2023-06-19 10:31 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-06-19
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	110（616版）
Resolution:	DUPLICATE	Degrated:	--
Severity:	Critical	Verified Version:	
Reproducibility:	Rarely	Fixed Version:	
Test Type:	Monkey Test	Root cause:	
Description			
【版本地址】 http://cdiot@192.168.87.46/Pre_figure/ReleaseBuild/Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp/user/20230616/1624			
【执行命令】 monkey --pkg-blacklist-file /sdcard/blackList.txt --hprof --throttle 500 -s 1234567 --pct-touch 35 --pct-motion 25 --pct-appswitch 30 --pct-pinchzoom 5 --pct-trackball 0 --pct-anyevent 5 --ignore-crashes --ignore-timeouts --ignore-security-exceptions --monitor-native-crashes --ignore-native-crashes --pct-syskeys 0 -v -v -v 12000000 2>/sdcard/error.txt 1>/sdcard/info.txt			
【测试结果】 monkey异常停止， 并设备未进入屏保			

History

#1 - 2023-06-19 11:07 - CD TEST-方永红

http://cdiot@192.168.87.46/Pre_figure/Test_Log/118830

#2 - 2023-06-24 13:41 - 物联网测试组_CDTS 唐霞

112release版本复现该问题
http://cdiot@192.168.87.46/Pre_figure/Test_Log/118830/tlog_sts40x190122_000280_0624115331.tar.gz

#3 - 2023-06-25 14:24 - CD APP-王营

- Status changed from New to ASSIGNED

【分析】

对比正常输出log 存在参数差异

06-14 11:45:03.419 1577 12634 D PowerManagerNotifier: onScreenPolicyUpdate: newPolicy=2

06-14 11:45:03.419 1577 12634 D PowerManagerNotifier: onWakeLockAcquired: flags=1, tag="AudioMix", packageName=audioserver, ownerUid=1041, ownerPid=0, workSource=null

06-14 11:45:04.110 1577 1796 D PowerManagerNotifier: onScreenPolicyUpdate: newPolicy=2

06-14 11:45:04.111 1577 1796 D PowerManagerNotifier: onWakeLockAcquired: flags=1, tag="NetworkStats", packageName=android, ownerUid=1000, ownerPid=1577,

```
workSource=null
06-14 11:45:04.138 1577 1796 D PowerManagerNotifier: onWakeLockReleased: flags=1, tag="NetworkStats", packageName=android, ownerUid=1000, ownerPid=1577,
workSource=null
06-14 11:45:04.138 1577 1796 D PowerManagerNotifier: onScreenPolicyUpdate: newPolicy=2
06-14 11:45:06.419 1577 2109 D PowerManagerNotifier: onWakeLockReleased: flags=1, tag="AudioMix", packageName=audioserver, ownerUid=1041, ownerPid=0,
workSource=null
06-14 11:45:06.419 1577 2109 D PowerManagerNotifier: onScreenPolicyUpdate: newPolicy=2
06-14 11:45:06.420 1577 5029 D PowerManagerNotifier: onWakeLockReleased: flags=1, tag="AudioMix", packageName=audioserver, ownerUid=1041, ownerPid=0,
workSource=null
06-14 11:45:06.420 1577 5029 D PowerManagerNotifier: onScreenPolicyUpdate: newPolicy=2
06-14 11:45:06.427 1577 3117 D PowerManagerNotifier: onWakeLockReleased: flags=1, tag="AudioMix", packageName=audioserver, ownerUid=1041, ownerPid=0,
workSource=null
06-14 11:45:06.427 1577 3117 D PowerManagerNotifier: onScreenPolicyUpdate: newPolicy=2
06-14 11:45:06.438 1577 3117 D PowerManagerNotifier: onWakeLockReleased: flags=1, tag="AudioMix", packageName=audioserver, ownerUid=1041, ownerPid=0,
workSource=null
06-14 11:45:06.438 1577 3117 D PowerManagerNotifier: onScreenPolicyUpdate: newPolicy=2
06-14 11:45:07.153 1577 3117 D PowerManagerNotifier: onScreenPolicyUpdate: newPolicy=2
06-14 11:45:07.154 1577 3117 D PowerManagerNotifier: onWakeLockAcquired: flags=1, tag="AudioMix", packageName=audioserver, ownerUid=1041, ownerPid=0,
workSource=null
06-14 11:45:07.155 1577 3117 D PowerManagerNotifier: onScreenPolicyUpdate: newPolicy=2
06-14 11:45:07.155 1577 3117 D PowerManagerNotifier: onWakeLockAcquired: flags=1, tag="AudioMix", packageName=audioserver, ownerUid=1041, ownerPid=0,
workSource=null
06-14 11:45:07.155 1577 10949 D PowerManagerNotifier: onScreenPolicyUpdate: newPolicy=2
06-14 11:45:07.156 1577 10949 D PowerManagerNotifier: onWakeLockAcquired: flags=1, tag="AudioMix", packageName=audioserver, ownerUid=1041, ownerPid=0,
workSource=null
06-14 11:45:07.156 1577 10949 D PowerManagerNotifier: onScreenPolicyUpdate: newPolicy=2
06-14 11:45:07.156 1577 10949 D PowerManagerNotifier: onWakeLockAcquired: flags=1, tag="AudioMix", packageName=audioserver, ownerUid=1041, ownerPid=0,
workSource=null
```

正常情况下：参数newPolicy 在收到变化时候，会先设置为2，然后启动屏保，变化为3，异常情况下newPolicy一直是2

【下一步】

分析newPolicy参数的修改逻辑

#4 - 2023-06-27 16:39 - CD APP-王营

- Assignee changed from CD APP-王营 to CD APP-王宏

#5 - 2023-06-27 16:44 - CD APP-王营

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD APP-王宏 to CD TEST-方永红

- Resolution changed from -- to DUPLICATE

Hi 永红,

此问题在jira中跟踪更新

<http://jira.human-horizons.com/browse/IOVDEV-33538?filter=-1>

#6 - 2023-08-04 10:40 - CD TEST-方永红

该问题在120、122、126、128版本上均未复现，先关闭

#7 - 2023-08-04 10:40 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

#8 - 2023-08-04 10:43 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED