

Status:	CLOSED	Start date:	2023-06-21
Priority:	Normal	Due date:	
Assignee:	SZTS_TEST 邹涛	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0112
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		
Description			
【问题出现时间】：2023.6.21 16:30 【开机次数】：第289次 【前提条件】： 副屏上电 【问题操作步骤】： 打开原神登录界面闪屏 【实际结果】：出现闪屏现象 【期望结果】：打开应用不会出现闪屏现象			

History
#1 - 2023-06-21 17:34 - CD TPM-王祥林
- Assignee changed from CD TPM-王祥林 to CD BSP-余霄
#2 - 2023-06-21 17:35 - CD TPM-王祥林
- Category set to BSP
#3 - 2023-06-21 18:32 - CD BSP-余霄
- Status changed from New to RESOLVED
已于测试确认，并非闪屏。
而是背景光显示效果问题，画面存在抖动。
该问题原因是动态帧率引起的
系统默认默认品质优先，选择的屏幕刷新率不是60HZ，与游戏刷新率不匹配。
在设置中选择、游戏模式设置、GPU设置、自定义模式、帧率选择60帧，验证背景光无抖动现象。
#4 - 2023-06-25 13:50 - CD TEST-方永红
- Assignee changed from CD BSP-余霄 to SZTS_TEST 邹涛
#5 - 2023-06-25 13:50 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

#6 - 2023-06-25 13:50 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
test.mp4	2.74 MB	2023-06-21	SZTS_TEST 邹涛
tlog_analysis.py	3.34 KB	2023-06-21	SZTS_TEST 邹涛
FSEM_000289_0110_0621163036.tar.gz	96.8 KB	2023-06-21	SZTS_TEST 邹涛
FSEM_000289_0111_0621163201.tar.gz	96.8 KB	2023-06-21	SZTS_TEST 邹涛