

Figure - Bug #118906

【AF】 【EVT3】 概率出现，识别不到点击或滑动操作

2023-06-27 17:20 - 物联网测试组_CDTs 唐霞

Status:	CLOSED	Start date:	2023-06-27
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	依赖客户及其供应商解决	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	114release (627)
Resolution:	--	Degrated:	--
Severity:	Major	Verified Version:	
Reproducibility:	Frequently	Fixed Version:	
Test Type:	Release Test	Root cause:	
Description			
【测试步骤】			
在设置中点击各个菜单			
在桌面/应用中滑动			
【预期结果】			
能正确识别点击或滑动操作			
【测试结果】			
无法识别到点击或滑动操作			

History

#1 - 2023-06-28 10:08 - CD FW 曹覃刚

- Category changed from CD-FW to BSP
- Assignee changed from CD FW 曹覃刚 to CD BSP-余霄

Hi 余霄

请检查复现视频

点击时不时会失效，测试屏幕报点是打开了的

有效时，有报点

无效时，没有报点

这个是屏幕硬件的问题，请确认

可能与下面这个更新固件的提交有关

<https://dev.thundercomm.com/gerrit/c/general/vendor/thundercomm/products/figure/+/209622>

#2 - 2023-07-12 10:39 - CD BSP-余霄

- Category changed from BSP to 依赖客户及其供应商解决
- Status changed from New to RESOLVED
- Assignee changed from CD BSP-余霄 to CD TEST-方永红

该问题为更新新固件后，驱动未更新灵敏度导致，该问题最新版本已修复

修改链接：

<https://dev.thundercomm.com/gerrit/c/general/kernel/msm-4.19/+/210914>

合入时间为:

目前新固件还存在一定问题，最新版本已回退。

#3 - 2023-08-24 17:13 - CDTS_TEST 王成
- Status changed from *RESOLVED* to *VERIFIED*

#4 - 2023-08-24 17:13 - CDTS_TEST 王成
- Status changed from *VERIFIED* to *CLOSED*

Files			
627.txt	40.9 MB	2023-06-27	物联网测试组_CDTS 唐霞
中科创达软件股份有限公司20230627-171746.mp4	7.06 MB	2023-06-27	物联网测试组_CDTS 唐霞