

Figure - Bug #119077

【AF】【PVT】【游戏模式】将支持小窗的应用删除至两个，打开游戏模式工具箱，删除的其中两个APP图标未消失

2023-07-21 16:51 - CDTs_Test 吴诗雨

Status:	ASSIGNED	Start date:	2023-07-21
Priority:	Normal	Due date:	
Assignee:	CDTS_TEST 王成	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	125release
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		
Description			
【前提条件】			
1、设备成功启动			
2、打开游戏模式			
【测试步骤】			
1、删除支持小窗的应用至两个			
2、进入游戏，打开工具箱			
3、查看支持小窗应用			
【预期结果】			
3、删除的APP不会出现在列表中			
【实际结果】			
3、斗鱼和QQ音乐HD的图标未消失，也无法打开。			
(查看设置—应用中 没有斗鱼和QQ音乐HD，桌面上也没有)			

History

#1 - 2023-08-10 14:24 - CD FW-程天颖
- Assignee changed from CD FW 曹覃刚 to CD FW-程天颖

#2 - 2023-08-14 17:24 - CD FW-程天颖
- Status changed from New to ASSIGNED

#3 - 2023-08-16 13:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
303186	general/platform/vendor/thundercom m/apps/GameMode	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:GameMode: Add add uninstall broadcast receiver logTC-RID: 1201-0204801IssueID: TS-R-BUG-119077Change-Id: I41e0a30a66392772b805e92d3d1ed7fbae8f3592			

#4 - 2023-08-17 19:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
304160	general/platform/vendor/thundercom/apps/GameMode	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:GameMode: Add add uninstall broadcast receiver logTC-RID: 1201-0204801IssueID: TS-R-BUG-119077Change-Id: I41e0a30a66392772b805e92d3d1ed7fbae8f3592(cherry picked from commit 57f4278b172761948702acd7869ddfb7d3e18174)			

#5 - 2023-10-25 14:03 - CD FW-程天颖
- Assignee changed from CD FW-程天颖 to CDTS_TEST 王成

【当前状态】
通过日志分析是由于没有收到应用卸载广播引起，但是缺少日志，已添加强化日
【下一步】
请帮忙复现，并提供日志信息

Files			
20230721-164722.jpg	80.6 KB	2023-07-21	CDTS_Test 吴诗雨
20230721-164727.jpg	64.2 KB	2023-07-21	CDTS_Test 吴诗雨
log1637.txt	14.1 MB	2023-07-21	CDTS_Test 吴诗雨