

Figure - Bug #119362

【AF】副屏启动后立即打开hicar应用，在初始化失败界面会提示“网络热点未连接成功，请重新打开中控台热点开关”

2023-09-07 18:05 - 物联网测试组_TSCD 王维

Status:	CLOSED	Start date:	2023-09-07
Priority:	Normal	Due date:	
Assignee:	移动测试一组_CDTs 刘强	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	0907DB
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-10-25
Reproducibility:	Every time	Root cause:	副屏连接中控热点失败提示逻辑。
Test Type:	ST		
Description			
【前置条件】 副屏与中控正常连接			
【操作步骤】 1.副屏正常下电重启 2.副屏重启成功立即点击hicar			
【实际结果】 hicar界面提示“网络热点未连接成功，请重新打开中控台热点开关”			
【预期结果】 初始化失败的界面不弹出异常提示			

History

#1 - 2023-10-25 13:41 - CD FW-廖涛

- Status changed from New to ASSIGNED
- Assignee changed from CD FW-程天颖 to CD FW-廖涛

#2 - 2023-10-25 16:27 - CD FW-廖涛

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-10-25
- Root cause set to 副屏连接中控热点失败提示逻辑。

■ Current conclusion

已处理，代码已入库。

■ My analysis

由于连接中控热点提示有误导性，所以去除掉。

■ Next action

麻烦测试验证。

#3 - 2023-10-25 16:29 - CD FW-廖涛

- Assignee changed from CD FW-廖涛 to 物联网测试组_TSCD 王维

#4 - 2023-10-25 16:29 - CDFW-廖涛
- Status changed from ASSIGNED to RESOLVED

#5 - 2023-10-25 16:37 - CDFW-廖涛
- Assignee changed from 物联网测试组_TSCD 王维 to 移动测试一组_CDTS 刘强

#6 - 2023-10-30 17:29 - 移动测试一组_CDTS 刘强
- Status changed from RESOLVED to VERIFIED

Release 150 验证通过

#7 - 2023-10-30 17:29 - 移动测试一组_CDTS 刘强
- Status changed from VERIFIED to CLOSED

Files			
1.png	1.57 MB	2023-09-07	物联网测试组_TSCD 王维