

Status:	CLOSED	Start date:	2023-09-18
Priority:	Normal	Due date:	
Assignee:	移动测试一组_CDTS 刘强	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	DB—0916
Resolution:	FIXED	Degrated:	No
Severity:	Major	Verified Version:	
Reproducibility:	Occasionally	Fixed Version:	2023-10-20
Test Type:	ST	Root cause:	HiCar 融合桌面功能引发的问题。
Description			
【测试步骤】 1. 打开抖音app 2. 打开设置 3. 关闭抖音小窗 4. 调节显示字体大小 【预期结果】 字体大小切换正常 【实际步骤】 偶现两次出现 “ "Quickstep"屡次停止运行 ”			

History
#1 - 2023-10-20 10:34 - CD FW-廖涛 - Status changed from New to RESOLVED - Assignee changed from CD FW 曹覃刚to 移动测试一组_CDTS 刘强 - % Done changed from 0 to 100 - Resolution changed from -- to FIXED - Degrated changed from -- to No - Fixed Version set to 2023-10-20 - Root cause set to HiCar 融合桌面功能引发的问题。 ■ Current conclusion 已处理，麻烦使用最新的副屏版本进行验证。 ■ My analysis HiCar 融合桌面功能开发，使用新接口导致的问题（ NonConfigInstance 获取方式调整 ）。 ■ Next action 麻烦测试验证。
#2 - 2023-10-30 17:34 - 移动测试一组_CDTS 刘强 - Status changed from RESOLVED to VERIFIED

#3 - 2023-10-30 17:34 - 移动测试一组_CDTS 刘强

- Status changed from VERIFIED to CLOSED

Files			
Screenshot_20230918-143325.png	478 KB	2023-09-18	移动测试一组_CDTS 刘强
tlog_iov0201017500006162025411a2212290000000611_001329_0918143455.tar.gz	3.94 MB	2023-09-18	移动测试一组_CDTS 刘强
tlog_iov0201017500006162025411a2212290000000611_001329_0918143633.tar.gz	2.23 MB	2023-09-18	移动测试一组_CDTS 刘强