

Status:	CLOSED	Start date:	2022-08-11
Priority:	High	Due date:	
Assignee:	项目二组_SD3 曾小文	% Done:	0%
Category:	EE	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	2022.08.07
Resolution:	--	Degrated:	--
Severity:	Major	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	Bring Up Test	Root cause:	
Description			
SLEEP_CLK/PM_SLP_CLK_IN频偏超规格要求: 实测29.666ppm，规格要求小于20ppm			

History

- #1 - 2022-08-22 14:23 - SZ HW Test-曾小文
- Assignee set to SZ-硬件二组_SD3 王苗
- #2 - 2022-08-23 16:24 - SZ HW Test-曾小文
- Subject changed from SLEEP_CLK/PM_SLP_CLK_IN频偏超规格要求 to 【Figure】【EVT】【SI】SLEEP_CLK/PM_SLP_CLK_IN频偏超规格要求
- #3 - 2022-09-05 10:40 - 项目二组_SD3 曾小文
- Status changed from New to RESOLVED
- #4 - 2022-09-05 11:08 - 项目二组_SD3 曾小文
- Status changed from RESOLVED to VERIFIED
- #5 - 2022-09-05 11:09 - 项目二组_SD3 曾小文
- Status changed from VERIFIED to CLOSED
- #6 - 2022-09-14 11:25 - CD TPM-申艳艳
- Category set to EE
- #7 - 2022-11-15 11:13 - SZ-硬件二组_SD3 王苗
- Status changed from CLOSED to VERIFIED
- Assignee changed from SZ-硬件二组_SD3 王苗 to 项目二组_SD3 曾小文
- 高通回复此误差满足要求
- #8 - 2022-11-28 11:38 - SZ HW Test-曾小文
- Status changed from VERIFIED to CLOSED
- 高通邮件回复无影响可关闭。

