

## Figure - Bug #113446

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

**【AF】【EVT】【设置】通过控制中心、通知中心、长按设置出现的弹窗选项，进入设置，再查看多任务管理器，会出现两个设置进程**

2022-11-01 14:02 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-11-01
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221115	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0042.X
Need_Info:	--	Degrated:	No
Resolution:	WORKSFORME	Verified Version:	
Severity:	Major	Fixed Version:	2022-11-01
Reproducibility:	Every time	Root cause:	现象与PIXEL一致，属于AOSP现象，不是问题
Test Type:	IT		

### Description

#### 【前提条件】

- 1、设备已开机
- 2、后台无进程

#### 【测试步骤】（以通知中心为例）

- 1、下划打开通知中心及控制中心
- 2、点击“前往通知设置”
- 3、通过上划手势进入多任务管理器
- 4、查看设置进程

#### 【预期结果】

- 4、有且只有一个设置进程

#### 【实际结果】

- 4、有两个设置进程卡片

PS：通过控制中心和长按设置出现的弹窗选项进入设置，再查看多任务管理器，也会出现两个设置进程

操作步骤同上

具体见截图

### History

#1 - 2022-11-01 17:38 - CD FW 曹覃刚

- Status changed from New to RESOLVED
- % Done changed from 0 to 100
- Resolution changed from -- to WORKSFORME
- Degrated changed from -- to No
- Fixed Version set to 2022-11-01
- Root cause set to 现象与PIXEL一致，属于AOSP现象，不是问题

已与测试沟通，该现象与PIXEL一致，是正常的现象

#2 - 2022-11-01 17:51 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

#3 - 2022-11-01 17:51 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

- Assignee changed from CD AF-陈羽杰 to CD TEST-方永红

#### Files

---

通、控.png	146 KB	2022-11-01	CD TEST-方永红
设置弹窗.png	240 KB	2022-11-01	CD TEST-方永红
1401.txt	3.94 MB	2022-11-01	CD TEST-方永红