

Figure - Bug #113945

测试 Test-IT # 111062 (New): V3.0功能测试

测试 Test-IT # 111069 (New): AF-V3.0--Launcher/SystemUI-小窗模式入口

【AF】【EVT】【小窗模式】在已打开一个小窗的基础上，启动新的小窗，小窗保持第一个小窗的模式（位置、大小）

2022-11-14 17:16 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-11-14
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	窗口定制	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0022.X
Severity:	Normal	Fixed Version:	2022-11-22
Reproducibility:	Every time	Root cause:	冷启动时 重新设置小窗的位置和大小
Test Type:	IT		
Description			
【前提条件】 1、设备已开机 2、后台无小窗进程 【测试步骤】 1、通过上划手势进入任务管理器 2、打开一个小窗应用 3、切换到mini模式 4、通过上划手势进入任务管理器 5、再打开一个小窗应用 【预期结果】 5、打开的小窗在默认位置、默认正常状态 【实际结果】 5、打开的小窗第一个小窗的模式（位置、大小） PS: 1、若第二个小窗为时钟，现象不同（见视频） 2、若在4、5之间加一步手动清除recent中的进程卡片，后续现象一致			

History

- #1 - 2022-11-21 14:10 - DL FW-张挽强
- Status changed from New to RESOLVED
- Assignee changed from DL FW-郝健 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2022-11-22
- Root cause set to 冷启动时 重新设置小窗的位置和大小
- #2 - 2022-11-22 11:13 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0022.X101

11.22
验证关闭

#3 - 2022-11-22 11:13 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
Phone-STS40X190122 2022-11-14 16-44-49.mp4	36.9 MB	2022-11-14	CD TEST-方永红
Phone-STS40X190122 2022-11-14 16-51-41.mp4	26.7 MB	2022-11-14	CD TEST-方永红