

Figure - Bug #114661

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114608 (New): 体验性测试

【AF】【EVT】【体验性测试】时钟小窗点击右上角的设置会对时钟的选项图标形成遮挡

2022-12-16 18:56 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-12-16
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	--
Resolution:	WORKSFORME	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、打开时钟小窗			
2、点击右上角的设置按钮			
【预期结果】			
1、弹出的设置项位于顶部时钟选项下方，不对选项图标形成遮挡			
【实际结果】			
4、弹出的设置项会对时钟的选项图标形成遮挡			

History

- #1 - 2022-12-20 17:37 - CD APP-王营
- Status changed from New to ASSIGNED
- Assignee changed from CD APP-王营to CD APP-王宏
- #2 - 2022-12-22 15:24 - CD APP-王宏
- Assignee changed from CD APP-王宏to CD TEST-方永红
- #3 - 2022-12-22 16:20 - CD TEST-方永红
- Status changed from ASSIGNED to RESOLVED
- Resolution changed from -- to WORKSFORME
- #4 - 2022-12-22 16:21 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- #5 - 2022-12-22 16:21 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files

1853.png	63.9 KB	2022-12-16	CD TEST-方永红
----------	---------	------------	-------------