

Figure - Bug #114829

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 112101 (New): AF-V2.0-Launcher/SystemUI-控制中心

【AF】 【EVT2】 【控制中心】 屏幕录制结束后，控制中心中多了“屏幕投射”控件

2022-12-26 19:15 - CD Test赵飞

Status:	CLOSED	Start date:	2022-12-26
Priority:	Normal	Due date:	
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_C sample_20230113	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2022-12-28
Reproducibility:	Every time	Root cause:	原生问题，已删除自动添加Tile的逻辑
Test Type:	ST		

Description
【前提条件】 1、设备已开机
【测试步骤】 1、打开控制中心 2、点击“屏幕录制”-开始录制 3、录制一段时间后，点击停止录制 4、查看控制中心中的控件
【预期结果】 4、控制中心中没有多出控件
【实际结果】 4、控制中心中多了“屏幕投射”控件
【日志】 截图见附件

History

#1 - 2022-12-27 18:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
172502	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings:Delete the automatically added TileDelete the automatically added TileTC-RID: 0301-0201903IssueID: TS-R-BUG-114829Change-Id: I7d4e033f70dd64c5e309ab313a6b80548e2e01f3			

#2 - 2022-12-27 18:59 - CD FW 曹覃刚

- Status changed from New to RESOLVED

- Assignee changed from *CD FW 曹覃刚* to *CD Test赵飞*
- % Done changed from 0 to 100
- Resolution changed from -- to *FIXED*
- Degrated changed from -- to *No*
- Fixed Version set to *2022-12-28*
- Root cause set to *原生问题，已删除自动添加Tile的逻辑*

#3 - 2022-12-28 15:18 - CD Test赵飞

- Status changed from *RESOLVED* to *VERIFIED*

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0063.X101
验证结果：PASS
屏幕录制结束后，控制中心中没有“ 屏幕投射 ”控件

#4 - 2022-12-28 15:18 - CD Test赵飞

- Status changed from *VERIFIED* to *CLOSED*

Files			
screenshot.png	433 KB	2022-12-26	CD Test赵飞