

Figure - Bug #116384

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111050 (New): AF-V2.0-Launcher/SystemUI-桌面管理

【AF】【EVT】【桌面管理】将时钟4*2微件大小调整为2*1时，微件内容显示不完整

2023-02-20 15:25 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-20
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	--
Resolution:	WONTFIX	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、添加一个时钟4*2大小的微件			
2、长按微件进入大小调整模式			
3、将时钟4*2微件大小调整为2*1			
【预期结果】			
3、微件内容随微件尺寸进行等比例缩放			
【实际结果】			
3、将时钟4*2微件大小调整为2*1时，微件内容显示不完整			

History

#1 - 2023-02-24 10:03 - 方案组-RD3_CDTs 王浩云
- Assignee changed from CD APP-王莹 to CD TEST-方永红

这个bug可以考虑关了，见昨天的邮件和更新后的PRD，此处属于应用内容的问题，可以不解

#2 - 2023-02-24 10:47 - CD TEST-方永红
- Status changed from New to RESOLVED
- Resolution changed from -- to WONTFIX

2.24
需求变更后不用处理

#3 - 2023-02-24 10:47 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

#4 - 2023-02-24 10:47 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED
- % Done changed from 0 to 100

Files

Phone-STX40X190078 2023-02-20 15-25-21.mp4	10 MB	2023-02-20	CD TEST-方永红
--	-------	------------	-------------