

Figure - Bug #117096

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【设置】【VC1】设置-显示页面按压状态和滚动条距离与ui不符

2023-03-22 19:20 - CDTs_Test 吴诗雨

Status:	CLOSED	Start date:	2023-03-22
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101)
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-03-24
Reproducibility:	Every time	Root cause:	RecyclerView 滚动条样式问题。
Test Type:	ST		

Description
【前提条件】
1、设备正常启动
【测试步骤】
1、进入设置
2、点击显示
3、长按操作模式
4、查看按压状态右侧与滚动条距离
【预期结果】
4、与ui图设计一致，两者距离5px
【实际结果】
4、按压状态和滚动条相接
【复现率】
3/3

History

#1 - 2023-03-24 10:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
189465	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Add paddingEnd to RecyclerView.Modify wallpaper preference to preference which with right arrow icon.TC-RID: 1201-0201813IssueID: TS-R-BUG-117096Change-Id: Ie0464a9e1f6ffd89da04db834393d568b58a5a1a			

#2 - 2023-03-24 10:24 - CD FW-廖涛

- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to CDTs_Test 吴诗雨

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-24
- Root cause set to RecyclerView 滚动条样式问题。

■ Current conclusion

已处理，代码已入库。

■ My analysis

RecyclerView 滚动条样式问题。

■ Next action

测试验证。

#3 - 2023-03-27 15:30 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

【验证版本】FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102.202303260013

【验证情况】按压状态和滚动条距离与ui相符，有距离，pass

#4 - 2023-03-27 15:30 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files			
13-1.png	140 KB	2023-03-22	CDTS_Test 吴诗雨
13.png	218 KB	2023-03-22	CDTS_Test 吴诗雨