

Figure - Bug #117181

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【屏保】【VC1】设置-显示-屏保-当前的屏保，点击任意一个屏保图片，全屏屏保下设为屏保和取消按钮位置与ui图不符

2023-03-27 16:35 - CDTS_Test 吴诗雨

Status:	CLOSED	Start date:	2023-03-27
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102(X102)
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-03-31
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	ST		

Description
【前提条件】 1、设备正常启动 【测试步骤】 1、进入设置-显示-屏保-当前的屏保-系统屏保 2、点击任意一个屏保的图片 3、查看全屏屏保模式下方的按钮，对比ui图 【预期结果】 3、设为屏保和取消按钮位置与ui图相符 【实际结果】 3、设为屏保和取消按钮位置与ui图不符

History

- #1 - 2023-03-30 19:16 - CD APP-王营
- Status changed from New to ASSIGNED
- % Done changed from 0 to 20
- #2 - 2023-03-31 10:18 - CD APP-王营
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王营 to CDTS_Test 吴诗雨
- % Done changed from 20 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-31
- Root cause set to 编码问题

■ Current conclusion

问题已修复

■ My analysis

VC1适配问题

■ Submit URL

<https://dev.thundercomm.com/gerriit/c/general/platform/vendor/thundercomm/apps/ScreenSaver/+/191003>

#3 - 2023-04-01 16:09 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

【验证版本】FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102.202304010020

【验证情况】设置-显示-屏保-当前的屏保，点击任意一个屏保图片，全屏屏保下设为屏保和取消按钮位置与ui图符合

#4 - 2023-04-01 16:11 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files				
2.png	1.04 MB	2023-03-27	CDTS_Test 吴诗雨	
2-1.png	1.06 MB	2023-03-27	CDTS_Test 吴诗雨	