

Figure - Bug #117824

【IOVDEV-25638】 【内部】 【解决方案】 【VC1】 【0076】 【实车】 【EE环境】 仪表和副屏息屏模式无法使用

2023-05-08 20:37 - CDTS_Test 吴诗雨

Status:	CLOSED	Start date:	2023-05-08
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	03.02.0076.C101
Need_Info:	TEST	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		
Description			
【出现时间】：2023.5.5 9：45 【前提条件】： 1、车机上电 【操作步骤】： 1、打开设置 2、点击仅仪表息屏 3、点击仅副驾屏 【实际结果】：仪表和副驾屏无法息屏 【期望结果】：仪表和副驾屏正常熄灭 【备注】：安卓日志已上云 【车架号】：LJD8BC3F6P0000365 【环境信息】：EE 【版本详情】：03.02.0076.C101 【复归方法】：无			

History

- #1 - 2023-05-09 11:12 - CD FW-程天颖
- Status changed from New to NEED_INFO
 - Assignee changed from CD FW-程天颖 to CDTS_Test 吴诗雨
 - Need_Info changed from -- to TEST

Hi,诗雨：

该问题不复现，请帮忙确认一下

- #2 - 2023-05-17 16:42 - CDTS_Test 吴诗雨
- Status changed from NEED_INFO to RESOLVED

- #3 - 2023-05-17 16:42 - CDTS_Test 吴诗雨
- Status changed from RESOLVED to VERIFIED

- #4 - 2023-05-17 16:42 - CDTS_Test 吴诗雨
- Status changed from VERIFIED to CLOSED

Files

image-2023-05-05-14-22-11-106.png	95.1 KB	2023-05-08	CDTS_Test 吴诗雨
飞书20230505-100034.mp4	4.27 MB	2023-05-08	CDTS_Test 吴诗雨