

Status:	CLOSED	Start date:	2023-06-06
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	窗口定制	Estimated time:	0.00 hour
Target version:			
Need_Info:	TEST	Found Version:	0106
Resolution:	INVALID	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
【环境信息】：EE环境			
【问题出现时间】：2023/06/06 09:35 第204次开机			
【前提条件】：电源ON			
【操作步骤】：			
1、打开开发者模式			
2、强制使用从右到左的布局方向			
3、打开小窗模式抖音			
【实际结果】			
全屏按钮和退出按钮重叠			
【期望结果】			
展示正常			
【备注】：			
【应用版本】：			
【硬件版本号】：不涉及			
【副屏版本号】：01.00.0106.C104			
【中控版本号】：03.02.0088.C103.02_userdebug_2306021732			
【中控VIN】HRYTTESTVINMGM403			
【第三方应用版本号】抖音 25.4.0			

#2 - 2023-06-07 15:14 - CD FW-鲁凯峰

- Status changed from New to NEED_INFO
- Assignee changed from CD FW-鲁凯峰 to CD TEST-方永红
- Need_Info changed from -- to TEST

由于没有需求说要做强制支持RTL模式适配,用户基本用不到这个模式,现在开发者选项已经被隐藏了,用户基本打不开.所以我们不会修改该问题

#3 - 2023-06-07 15:20 - CD TEST-方永红

- Status changed from NEED_INFO to RESOLVED
- Resolution changed from -- to INVALID

#4 - 2023-06-07 15:20 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

#5 - 2023-06-07 15:21 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

小窗模式，全屏按键和退出键重合.png	1.53 MB	2023-06-06	CD TEST-方永红
---------------------	---------	------------	-------------