

Figure - Bug #119572

【AF】【PVT】【Settings】开启小窗模式后，进入清洁模式，小窗模式仍然可以使用

2023-11-01 17:58 - 移动测试一组_CDTS 刘强

Status:	RESOLVED	Start date:	2023-11-01
Priority:	Normal	Due date:	
Assignee:	CDTS_TEST 王成	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	150
Resolution:	FIXED	Degrated:	No
Severity:	Major	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-11-16
Test Type:	ST	Root cause:	窗口层级问题。
Description			
【测试步骤】			
1. 设备烧写150版本			
2. 打开小窗模式			
3. 通知栏进入清洁模式			
【预期结果】			
清洁模式下不显示小窗应用			
【实际结果】			
清洁模式下显示小窗应用，且可以正常使用			

History

#1 - 2023-11-08 18:23 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
326562	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: Adjust the display layer of the cleaning mode page.TC-RID: 1201-0201903IssueID: TS-R-BUG-119572Change-Id: I4d1106fc16c3604e580254cbb057bb447a2df037			

#2 - 2023-11-08 22:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
326553	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxi0510@thundersoft.com
AF:QuickSettings: Adjust the display layer of the cleaning mode page.TC-RID: 1201-0201903IssueID: TS-R-BUG-119572Change-Id: I4d1106fc16c3604e580254cbb057bb447a2df037(cherry picked from commit 12b86125d18f6f1e96f31345ea40213e1307ed45)			

#3 - 2023-11-16 18:59 - CD FW-廖涛

- Category set to CD-FW
- Status changed from New to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CDTS_TEST 王成
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degraded changed from -- to No
- Fixed Version set to 2023-11-16
- Root cause set to 窗口层级问题。

■ Current conclusion

已处理，代码已入库。

■ Next action

麻烦测试验证。